

Extract from Vitaplay inspection 29/2/24

Summary

There was little to surprise us thanks to the weekly inspections. We knew 3 of the 4 'medium' risks.

RECOMMENDATION Contact Caloo (manufacturer) for cross rider repair

Deal with picnic table when a builder comes in to do work on The Pavilion

Wait for further recommendations from the Community Hub WG regarding the table tennis table (per last meeting)

Make own assessment of crush risk at pedestrian gate

All other matters to await whole area plan from CH WG

Finding Summary

Alderbury Recreation Ground Findings

Asset	Finding Title	Creation Date	Risk Level
Cross Rider - Fitness Equipment	Item - Bearings Worn	05/03/2024 13:56:36	Medium
Round Picnic Table 3	Item - Damaged	06/03/2024 08:44:19	Medium
Table Tennis Table	Item - Damaged	06/03/2024 12:04:05	Medium
Timber Pedestrian Gate	Moving Parts - Crush	06/03/2024 12:29:11	Medium
Basket Ball Post	Item - Requires cleaning	05/03/2024 12:59:59	Low
Basket Ball Post - Surface	Surface - Moss	05/03/2024 13:04:05	Low
Basket Swing Frame	Rope - Metal core exposed	05/03/2024 13:06:57	Low
Basket Swing Frame - Surface	Surface - Worn	05/03/2024 13:10:03	Low
Body Twist - Fitness Equipment	Item - Bearings Worn	05/03/2024 13:12:04	Low
Body Twist - Fitness Equipment	Item - Re-paint	05/03/2024 13:13:57	Low
Cableway	Item - Requires cleaning	05/03/2024 13:28:40	Low
Cableway - Surface	Surface - Moss	05/03/2024 13:32:57	Low
Cradle Swing Frame	Item - Requires cleaning	05/03/2024 13:46:39	Low
Cradle Swing Frame - Surface	Surface - Moss	05/03/2024 13:50:25	Low
Cross Rider - Fitness Equipment	Item - Re-paint	05/03/2024 14:07:24	Low
Cradle Swing Frame - Surface	Ground Eroded	05/03/2024 14:09:05	Low
Cradle Swing Frame - Surface	Surface - Perimeter of Surface Shrunk from Edgings	05/03/2024 14:10:49	Low
Fun Box with Rails	Item - Re-paint	05/03/2024 14:16:40	Low
Fun Box with Rails	Item - Graffiti - Present	05/03/2024 14:18:44	Low
Grind Rail	Item - Rusting in places	05/03/2024 14:20:32	Low
Fun Box with Rails	Other / Miscellaneous	05/03/2024 14:52:22	Low
Junior Multi-Unit	Item - Timber rotting	05/03/2024 14:55:38	Low
Junior Multi-Unit - Surface	Surface - Perimeter of Surface Shrunk from Edgings	05/03/2024 15:02:30	Low
Junior Multi-Unit - Surface	Ground Eroded	05/03/2024 15:04:09	Low
Mesh Fencing	Fencing - Panel damaged	05/03/2024 15:06:48	Low
Quarter Pipe	Concrete - Edges - Damaged	05/03/2024 22:30:38	Low
Rider - Fitness Equipment	Item - Rusting in places	05/03/2024 22:35:45	Low
Round Picnic Table 1	Other / Miscellaneous	06/03/2024 08:35:20	Low
Round Picnic Table 2	Other / Miscellaneous	06/03/2024 08:42:14	Low

Asset	Finding Title	Creation Date	Risk Level
Rower - Fitness Equipment	Item - Re-paint	06/03/2024 08:46:49	Low
Seesaw - Surface	Surface - Perimeter of Surface Shrunk from Edgings	06/03/2024 08:48:40	Low
Senior Multi-Unit - Surface	Surface - Perimeter of Surface Shrunk from Edgings	06/03/2024 10:32:42	Low
Senior Multi-Unit - Surface	Moss/algae present	06/03/2024 10:40:19	Low
Skate Park Bin	Item - Loose in Ground	06/03/2024 10:58:48	Low
Skate Park Surface	Surface - Cracking	06/03/2024 11:58:01	Low
Spring Rocker	Item - Missing	06/03/2024 11:59:34	Low
Table Tennis Table	Item - Cracked	06/03/2024 12:10:19	Low
Table Tennis Table	Item - Re-paint	06/03/2024 12:11:42	Low
Twin Bench	Item - Re-paint	06/03/2024 12:31:59	Low
Quarter Pipe	Item - Bent	06/03/2024 12:33:48	Low
Play Area Sign 1	Item - Cracked	05/03/2024 15:08:53	Very Low
Play Area Sign 2	Item - Graffiti - Present	05/03/2024 15:10:07	Very Low
Quarter Pipe	Item - Graffiti - Present	05/03/2024 22:22:26	Very Low
Small Quarter Pipe	Item - Graffiti - Present	06/03/2024 12:39:18	Very Low