

# Inspections

## Equipment

### Playsafety RoSPA report 20.9.23

NOTES

	<u>Comments</u>	<u>Action/risk</u>	
<u>ADULT GYM</u>			
Black benches			
Body twist			
Cross trainer	bearings worn	monitor/medium	up a risk level
Rower			
Bench			
Rider			
<u>PLAY AREA</u>			
Litter bin			
Wooden bench	loose fittings: inspector could raise a plank	repair/low	
Age sign			
Ownership sign	graffiti	remove	
Cableway			inspector cannot investigate easily but repaired recently
Basket swing	chain wear	monitor/medium	risk up on 2022
	exposed metal rope	monitor/medium	risk up on 2022
	trip points on surface	build up earth/low	
	seat at wrong height	adjust height/low	
Rocker	trip points on surface	make level/low	
	missing caps	replace/low	EH says never there
Toddler multiplay	missing caps	replace/low	
		tighten or	
	fixtures loose (roof)	replace/medium	
	paintwork worn	repaint/low	
	ramp logs decaying	repair/low	
Toddler swing			
		rub down & treat/low	
Junior multiplay	laminates damage	repaint/low	
<i>NOTE this equipment does not meet modern standards</i>	paintwork worn		
	decaying timber		
	(overall)	monitor/low	
	wetpour shrinkage	medium	
	platform is unsafe	high	
Junior swing	chain wear	monitor/low	
	trip points on surface	make level/low	
	wetpour surface damaged	repair/medium	Vitaplay asked to quote
		fill or	
Rocker/seesaw	wetpour shrinkage	repair/medium	new

## SKATE PARK

Litter bin			
Path	cracking	repair/low	
Sign			
Table tennis table	damaged ground to unit	repair/medium	up a level
Quarter pipe	transition offensive graffiti <i>Insepctor has general concern about the design of this unit</i>	modify/low as poss remove/low	
Driveway			
Grind bench			
Spine ramp	paintwork worn	repaint/low cut off or file	
Grind rail	projecting bolt thread loose fixtures	down/low tighten/low	
<u>OTHER</u>			
Basketball post	warning sign required	fit/low	
Grass & general surroundings			
Pathways			
Picnic benches	broken	needs repair/medium	new but we plan to have these removed