

Alderbury Parish Council

Agenda item 137.24c

Alderbury Recreation Ground Inspection Findings

Shows items mentioned by professional inspectors as having a risk other than low, including where our inspectors found other issues

NB Graffiti is a problem on signage and the skatepark. Not a risk as such, but may be worth tackling.

Safety surface shrinkage throughout. Inspectors seem to vary on their assessment of this as a risk.

EQUIPMENT	CONCERN	RISK – Vitaplay May	RISK – RoSPA October	What our own inspections say (if different)	Further observations
Cross Rider	Bearings Worn	Medium	Medium		November agenda to approve full gym inspection & minor repairs
				Joint at LH pedal loose	----- ditto -----
Round Picnic Table 3	Damaged	Medium	Medium		Now in the garage
Table 2				Medium - damaged	
Table Tennis Table	Damaged	Medium	Medium		Will only be addressed as part of the wider playground rethink
Timber Pedestrian Gate Moving Parts	Crush	Medium	Didn't check		EH arranged for MR Fencing to fix this – not sure if it has been
Basket Swing Frame Rope	Metal core exposed	Low	High		Is temporary repair enough?
Junior swing	Table should not be there		High		Removed
	Debris in hedge behind			Medium – needs removing	HAS THIS BEEN DONE?
Driveway	Concrete edging poor condition		Medium		} If you have lived with the risks seemingly inherent in the poor design of this equipment for a long time. } } }
	Lack of radius or chamfer on edges + gaps		Medium		
Quarter pipe	Ground to unit gap		Medium (higher side)		

EQUIPMENT	CONCERN	RISK – Vitaplay May	RISK – RoSPA October	What our own inspections say (if different)	Further observations
Seesaw	Perimeter of Surface Shrunken from edging	Low	Medium		
Junior Multi	Perimeter of Surface Shrunken from edging	Low	Medium		
	Roof not properly fastened		Medium	CR noted this at the toddler unit??	NEED TO CHECK BOTH ROOVES
Spring rocker	Surfacing shrinkage		Medium		